Approved For Release 2002/06/13 : CIA-RDP68B00724R000200240025-7

	<u> </u>		
		IDEA-3343-66 Copy 6	
		4 October 1966	
MEMORANDUM FOR:	Comptroller, OSA		
SUBJECT:	Technical Representa	tive Requirements	
apparently, much Itek Tech Rep su	as been considerable confusion remains on pport of the Delta II pts to clarify the si	the subject of I cameras. This	
in the inventory by the end of No to five. If an	. With the delivery vember, this quantity operational requiremes, Itek maintenance t	will be increased ent still exists	25X
		-	<u> </u>

25X1

	Approved For Release 2002/06/13 : CIA-RDP68B00724R000200240025-7	
	SECRET	25X1
	IDEA-3343-66 Page 2	
25X1 25X1 25X1	from three locations since February 1966. This was brought about by the loan of a Delta III camera, spares and contract maintenance support for use by the Air Force at This resulted in placement of Delta III equipments and personnel at Detachment G and Detachment H, with the personnel at being rotated every thirty to sixty days. This type of operation has more than proven the need for the technicians with the being required to maintain team integrity, in the event a regular team member was absent for reasons of sickness, leave or compensatory	25X1 25X1 25X1
25X1 25X1	5. The reduction in numbers of technicians for support of the Delta III equipment, would immediately constrict the dual staging capability with this equipment and would impact unfavorably on the maintenance support of either Detachment "G", "H" or of As OSA has been committed to support this would leave one maintenance team to support Delta III equipment at Detachments "G" and "H".	25X1
25X1	6. As long as the mission directives remain as they are and OSA is required to support Air Force at the requirement for technicians will continue.	25X1
		25X1
25X1	Acting Deputy for Materiel, OSA MD/M/GSA Distribution: #1 - COMPT/CSA #2 - D/O/OSA #3 - IDEA/O/CSA #4 - D/M/OSA #5 - D/M/OSA (Chrono) #6 - RB/OSA	
	Approved For Release 2002/06713 : CIA-RDP68B00724R000200240025-7	25X1